T8 EXT

MODEL

Model: 9.5T8/2F/xxx/EXT
10.5T8/3F/xxx/EXT
11.5T8/4F/xxx/EXT
14T8/4F/xxx/EXT
14.5T8U6/xxx/EXT

Where xxx means 824-965 which indicates CRI and color temperature



EMERGENCY DRIVER COMPATIBILITY

Model: 9.5T8/2F/xxx/EXT 11.5T8/4F/xxx/EXT

Brand	Model	Compatibility
Iota	ILB-CP05-B	Comptible
	ILB-CP07-B	Comptible
	ILB-SL-CP05	Comptible
	ILB-SL-CP07	Comptible
Fulham	FHSCP-UNV-10.7WL	Comptible
	FHSCP-UNV-13.7WL	Comptible
	FHSCP-UNV-17WL	Comptible

EMERGENCY DRIVER COMPATIBILITY

Model: 10.5T8/3F/xxx/EXT

Brand	Model	Compatibility
Iota	ILB-CP05-B	Comptible
	ILB-CP07-B	Comptible
	ILB-CP10-B	Comptible
	ILB-SL-CP05	Comptible
	ILB-SL-CP07	Comptible
	ILB-SL-CP10	Comptible
Fulham	FHSCP-UNV-10.7WL	Comptible
	FHSCP-UNV-13.7WL	Comptible
	FHSCP-UNV-17WL	Comptible

GREENCREATIVE

T8 EXT

EMERGENCY DRIVER COMPATIBILITY

Model: 14T8/4F/xxx/EXT

Brand	Model	Compatibility
Iota	ILB-CP05-B	Comptible
	ILB-CP07-B	Comptible
	ILB-CP10-B	Comptible
	ILB-SL-CP05	Comptible
	ILB-SL-CP07	Comptible
Philips	BSL310C-DF	Comptible
Fulham	FHSCP-UNV-10.7WL	Comptible
	FHSCP-UNV-13.7WL	Comptible
	FHSCP-UNV-17WL	Comptible

EMERGENCY DRIVER COMPATIBILITY

Model: 14.5T8U6/xxx/EXT

Brand	Model	Compatibility
Iota	ILB-CP05-B	Comptible
	ILB-CP07-B	Comptible
	ILB-CP10-B	Comptible
	ILB-SL-CP05	Comptible
	ILB-SL-CP07	Comptible
	ILB-SL-CP10	Comptible
Philips	BSL310	Comptible
	BSL310M	Comptible
	BSL310C	Comptible
	BSL310C-DF	Comptible
Fulham	FHSCP-UNV-10.7WL	Comptible
	FHSCP-UNV-13.7WL	Comptible
	FHSCP-UNV-17WL	Comptible

GREEN CREATIVE has provided this emergency ballast compatibility chart for guidance when selecting an emergency ballast and lamp combination. Lamps were tested for compatibility with the above listed emergency ballasts. Emergency ballasts that do not appear on the chart might still be compatible but have not been tested. All testing has been performed with a stable main supply. The quality of the local main, existing installation and wiring, as well as different manufacturer versions of the above emergency ballasts may affect lamp performance. Since no assurance can be provided regarding these factors, it is a general recommendation to perform a test on-site prior to installing the LED lamps.